

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.**

No. A.E.C.W.U/2021-22/QDate : 15/6/2021

It is certified that an inspection team headed by Ms. Anil Singare
(Name of Officers with designation) from NAGAR NIGAM, JABALPUR (Name of
Department/Office) inspected the KENDRIYA VIDYALAYA VEHICLE FACTORY, JABALPUR,
SECTOR- 2 VEHICLE FACTORY ESTATE JABALPUR (M.P.) PIN CODE 482009 (Name &
Address of the School) on 14.06.2021 and found that the KENDRIYA
VIDYALAYA VEHICLE FACTORY, JABALPUR (Name of school) has safe drinking water
facilities for the students and members of staff of the institution and is maintaining the hygienic
sanitation condition in the school building & the campus as per the norms prescribed by the
Central/State/U.T Govt.

The above valid for a period of 03 years from date of issue

Signature with Seal :

ASingare
15/6/21

Name :

अनिल सिंगारे

Designation :

सहायक संतजल प्रवाह विभागनगर निगम, जबलपुर

To

KENDRIYA VIDYALAYA VEHICLE FACTORY
SECTOR- 2 VEHICLE FACTORY ESTATE,
JABALPUR (M.P.) PIN CODE 482009

16.6.2021
Principal
केन्द्रीय विद्यालय/ Kendriya Vidyalaya
वाहन निर्माणी/ Vehicle Factory
86 जबलपुर (म.प्र.)/Jabalpur (M.P.)